## 1989 part 4

propeller strike PSA showed boating in a bad light.

## 8. 1989 NBSAC Propeller Guard Subcommittee: Findings

## The Charge to the Subcommittee Why the Subcommittee Rejected Guards **Cross Sectional Area** The subcommittee notes, "Up to 80% of underwater impacts The subcommittee was charged to: occur at normal operating speeds." (this unproven Snyderism is disputed by USCG's Purcell & Lincoln report and by BARD data). 1. "Review available data on prevention of propeller-strike accidents and the Coast Guard study of various The subcommittee report stated "boats and motors should be methods of shrouding propellers to prevent contact designed to incorporate technologically feasible safety features to with a person in the water." avoid or minimize the consequences of inexperienced or negligent operation, without at the same time (a) creating some other hazard. 2. "Assess the arguments for and against some form of (b) materially interfering with normal operations, or (c) being at mechanical guard to protect against propeller strikes." economic cost disproportionate to the particular risk." Ten points to be considered were identified. The first two Proponents of propeller quards say quards meet the requirements points were: above. The subcommittee report said guards did not meet the requirement because: "What is the incidence of such accidents?" (propeller A. Fine mesh guards are not feasible above 2-3 mph. strike statistics) 1. 2. Wide mesh guards, spaced bars, or ring guards may prevent Β. "Is there a trend to more or fewer such accidents?" propeller cuts but cause blunt trauma injury which becomes increasingly significant at speeds over 10mph Mercury Marine misled the subcommittee by furnishing partial Event 1 fatality statistics, greatly understating 3. "Either guard (mask or ring type) presents an underwater propeller fatalities. Not a single accident statistic is provided profile of significantly larger frontal area, thereby in the body of the subcommittee's final report. No efforts increasing the chances of contact." (see right) were made to account for injuries or unreported accidents. blade tip clearance is extreme. 4. Ring type guards may entrap arms or legs. No mention is made of propeller accident trends in the final report even though BARD reports of propeller strikes were 5. Operators of "guard equipped" boats may have a false sense rapidly increasing in that era. (see chart on **1989 part 2**) of security when approaching people in the water at slow speeds resulting in the guard striking them or entrapping a body appendage. **Recommendations of the Subcommittee** 6. Above 10 mph, drag results in significant loss of power and speed. Increased fuel consumption is required to reach the The subcommittee's first three recommendations are below: same speeds. 7. Kort Nozzles can increase efficiency at low speeds. They are 1. "The U.S. Coast Guard should take no not propeller guards. regulatory action to require propeller guards." 8. Water jet propulsion removes the propeller at a minimum cost 2. "The U.S. Coast Guard should, through improved of 25 percent loss of efficiency and creates handling accident reporting and analysis, develop a complete problems. and comprehensive data base on underwater impact See the large Mercury outboards below. accidents." 9. No known materials can make guards or propellers "soft" to absorb energy while they still serve their intended purpose. 3. "The U.S. Coast Guard should implement necessary 10. Seat belts could prevent ejections, but could result in steps to have included in national and state level drownings if the boat turns over. educational and awareness campaigns the information regarding potential hazards associated with careless or 11. Guards would have to be hydrodynamically and structurally negligent boat operation. Such programs should be on a compatible with the intended propulsion unit. Retrofitting continuing basis and be as vivid as possible in depicting boats in the field would require a vast number of guard underwater impact accident scenarios." models at a prohibitive cost. In 2010 USCG produced a vivid propeller strike video 12. Waterskiing and Swimming are activities and do not describe titled, Don't Wreck Your Summer. The boating industry boat types. Boats are multipurpose which prevents the use of quickly rejected the Public Service Announcement (PSA) an Off-On guard. If guards were removable, they would be and had USCG take it down. The industry said the

removed which could result in overpowering a boat.

The NBSAC propeller guard subcommittee emphasized guards could strike people that might not have been struck by the open propeller due to their larger cross sectional area. They said blunt trauma from striking guards could be worse than the clean cuts made by open propellers.

No testing was performed to prove this, or to prove it was even possible to be within the narrow donut shaped area between the propeller blade tips and the propeller guard and not be sucked into the propeller anyway.

The subcommittee report stated, "Due to its revolutions, a propeller generally produces a series of evenly spaced cuts which are relatively easier to repair surgically." (another unproven Snyderism). No mention was made of those who bled out from propeller strikes and drowned, of water borne bacterial infections of propeller wounds, of dozens of surgeries over decades sometimes required by propeller victims, or of the lifetime of challenges faced by amputees.

The subcommittee said adding a propeller guard could triple the forward facing cross sectional area of the propeller (black circle vs red dashed circle below). That is only close to true when the propeller is stationary and



Today, the industry mounts several very large outboards on boats with no concern for submerged cross sectional area.

